

ANN ARBOR MUNI (ARB)(KARB) 3 S UTC-5(-4DT) N42°13.38' W83°44.74'

839 B NOTAM FILE ARB

RWY 06-24: H3505X75 (CONC-GRVD) S-45, D-70 MIRL

RWY 06: REIL. PAPI(P4L)—GA 3.0° TCH 20'.

RWY 24: VASI(V2L)—GA 3.0° TCH 20'. Tree.

RWY 12-30: 2750X110 (TURF) 0.6% up NW

RWY 30: Tree.

SERVICE: S4 FUEL 100LL, JET A+ OX1, 2, 3, 4 LGT When ATCT clsd ACTVT REIL Rwy 06, PAPI Rwy 06, VASI Rwy 24, MIRL Rwy 06-24—CTAF.

AIRPORT REMARKS: Attended Apr-Oct 1300-0100Z†, Nov-Mar 1300-2300Z†. Trml open 1200Z†-dusk. Deer and lrg birds on and invof arpt. When ATCT clsd confirm snow removal ops and winter conditions—CTAF. No snow removal for Rwy 12-30. Rwy 24 runup area, first 200' of Twy A, Twy A1 between Twy A and Rwy 24 hold line not vsb fm twr. Rwy 12-30 marked with 3' yellow cones. SAID in use. Operate transponders with altitude reporting mode and ADS-B (if equipped) enabled on all airport surfaces.

AIRPORT MANAGER: 734-794-6312

WEATHER DATA SOURCES: ASOS (734) 668-7173 LAWRS.

COMMUNICATIONS: CTAF 120.3 ATIS 134.55 UNICOM 123.0

® **DETROIT APP/DEP CON** 118.95

TOWER 120.3 (1300-0100Z†) **GND CON** 121.6 **CLNC**

DEL 121.6

CLEARANCE DELIVERY PHONE: For CD when ATCT is clsd ctc Detroit Apch at 734-955-1404.

AIRSPACE: CLASS D svc 1300-0100Z†; other times CLASS G.

RADIO AIDS TO NAVIGATION: NOTAM FILE LAN.

SALEM (L) (L) VORTACW 114.3 SVM Chan 90 N42°24.52' W83°35.63' 214° 13.0 NM to fld. 956/3W.

TACAN AZIMUTH unusable:

215°-255° byd 10 NM

VOR unusable:


094°-121° byd 10 NM blo 5,000'

094°-121° byd 20 NM blo 8,000'

DME unusable:

099°-115° byd 15 NM blo 5,000'

099°-115° byd 20 NM blo 8,000'



DETROIT
COPTER
L-28J, A
IAP, AD

ANTRIM CO (See BELLAIRE on page 159)

ARNOLD FLD (See CROSWELL on page 171)