

IOLA**CENTRAL CO** (68C) 4 E UTC-6(-5DT) N44°30.29' W89°01.55'

GREEN BAY

882 NOTAM FILE GRB

RWY 05-23: 2493X60 (TURF)

RWY 05: Trees.

RWY 23: Trees.

RWY 09-27: 1783X40 (TURF) 0.6% up E

RWY 09: Trees.

RWY 27: Tree.

RWY 12-30: 1745X40 (TURF)

RWY 12: Trees.

RWY 30: Trees.

AIRPORT REMARKS: Unattended. Arpt CLOSED to wheeled acft when rwys covered with snow or ice. Deer on and invof arpt.

Rwy 09 marked with orange cones.

AIRPORT MANAGER: 920-572-0045**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**IOWA CO** (See MINERAL POINT on page 371)**JANA** (See EDGERTON on page 349)**JANESVILLE****SOUTHERN WISCONSIN RGNL** (JVL)(KJVL) 3 SW UTC-6(-5DT) N42°37.22' W89°02.49'

CHICAGO

808 B Class IV, ARFF Index A NOTAM FILE JVL

H-5D, L-28H

RWY 14-32: H7302X150 (CONC-GRVD) S-112, D-147, 2S-175, 2D-255 PCR 440 R/B/X/T HIRL No

IAP, AD

Part 121/Part 380 Ops

RWY 14: REIL. PAPI(P4L)—GA 3.0° TCH 55'.

RWY 32: MALSR. VASI(V4L)—GA 3.0° TCH 51'.

RWY 04-22: H6701X150 (ASPH-GRVD) S-44, D-60, 2S-165, 2D-105 PCR 170 R/D/X/T HIRL No Part 121/Part 380

Ops

RWY 04: MALSR. PAPI(P4L)—GA 3.0° TCH 54'.

RWY 22: REIL. PAPI(P4L)—GA 3.0° TCH 45'. Tree.

RWY 18-36: H5004X75 (ASPH) S-37, D-58, 2D-104 PCR 130 F/C/X/T MIRL No Part 121/Part 380 Ops

RWY 18: Road.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 04: TORA-6701 TODA-6701 ASDA-6701 LDA-6701

RWY 14: TORA-7302 TODA-7302 ASDA-7302 LDA-7302

RWY 18: TORA-5004 TODA-5004 ASDA-5004 LDA-5004

RWY 22: TORA-6701 TODA-6701 ASDA-6701 LDA-6701

RWY 32: TORA-7302 TODA-7302 ASDA-7302 LDA-7302

RWY 36: TORA-5004 TODA-5004 ASDA-5004 LDA-5004

SERVICE: S4 FUEL 100LL, JET A LGT ACTVT MALSR Rwy 04 & 32; REIL Rwy 14 & 22; VASI Rwy 32; HIRL Rwy 04-22 & 14-32; MIRL Rwy 18-36—CTAF. When ATCT clsd HIRL Rwy 04-22 preset to low instst; incr instst—CTAF. PAPI Rwy 04, 14, & 22 opr consly.**AIRPORT REMARKS:** Attended 1300-2130Z±. Conds unmnt 2130-1300Z±, wkend and fed hol. Rwy 04-22, Rwy 14-32 and Rwy 18-36, 90 day PPR for unsked ACR ops gtr than 30 pax seats—amgr. Lgt sport acft with cruise speed of 60 mph or less enter tfc pat at 500' AGL. Rwy 32 and Rwy 36 apch ends are closely aligned, verify rwy and hdg bfr dep. Rwy 04-22 aprons and ramps rstd to 155 DTW gross wt.**AIRPORT MANAGER:** 608-757-5768**WEATHER DATA SOURCES:** AWOS-3 (608) 758-1723 LAWRS (1200-0300Z±).**COMMUNICATIONS:** CTAF 118.8 ATIS 128.25 UNICOM 122.95

Ⓡ ROCKFORD APP/DEP CON 121.0

JANESVILLE TOWER 118.8 (1200-0300Z±) GND CON 121.65 CLNC DEL 121.65

CLNC DEL 121.65 (when twr clsd)

AIRSPACE: CLASS D svc 1200-0300Z±; other times CLASS G.**RADIO AIDS TO NAVIGATION:** NOTAM FILE JVL.

JANESVILLE (L) (L) VORW/DME 114.3 JVL Chan 90 N42°33.48' W89°06.32' 034° 4.7 NM to fld. 932.3E.

VOR unusable:

001°-089°

155°-175° byd 15 NM

282°-000° byd 30 NM blo 3,000'

ILS 109.1 I-JVL Rwy 04. Class IE. Unmonitored when ATCT clsd.

ILS/DME 111.35 I-REE Chan 50(Y) Rwy 32. Class IE. Unmonitored when ATCT clsd. LOC unusable byd 19° right of course.