

RENNER FLD/GOODLAND MUNI (See GOODLAND on page 98)

ROOKS CO RGNL (See STOCKTON on page 137)

ROSE HILL

BUTLER AIRPORT (6KS) 3 E UTC-6(-5DT) N37°33.56' W97°03.89' WICHITA
1310 NOTAM FILE FSS Not insp.
RWY 01-19: 2577X40 (TURF) RWY LGTS(NSTD) 1.3% up S
RWY 01: Road. Rgt tfc.
AIRPORT REMARKS: Attended ireg. All arpt ops are suspended during wet sfc conditions. All tlc pattern flown E of arpt. All traffic remain east of rwy. Arpt ops are ltd to sngl eng lgt acft of 3250 lbs max gross ldg wt unless specifically auth prior to ldg. Any objectionable damage to the turf rwy or turnarounds must be repaired by the offending pilot or acft owner to the satisfaction of the butler arpt mgr or president.
AIRPORT MANAGER: 316-925-2215
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD etc Wichita Apch at 316-350-1520.

COOK AIRFIELD (K50) 2 W UTC-6(-5DT) N37°33.92' W97°10.48' WICHITA
L-15D
IAP
1342 B NOTAM FILE ICT
RWY 17-35: H3471X40 (ASPH) S-2 MIRL
RWY 17: PAPI(P2L)—GA 3.5° TCH 24'. Thld dspcd 198'. Trees.
RWY 35: PAPI(P2L)—GA 3.0° TCH 17'. Road. Rgt tfc.
RWY 01-19: 1600X50 (TURF) 0.7% up S
RWY 01: Hangar.
RWY 19: Tree.
SERVICE: FUEL 100LL, MOGAS LGT ACTVT bcn—123.5. ACTVT PAPI Rwy 17 and Rwy 35; MIRL Rwy 17-35—123.5.
AIRPORT REMARKS: Unattended. Fuel Self-svc. Parachute Jumping.
AIRPORT MANAGER: 316-706-6131
COMMUNICATIONS: CTAF/UNICOM 122.8
® **WICHITA APP/DEP CON** 134.8
CLEARANCE DELIVERY PHONE: For CD etc Wichita Apch at 316-350-1520.
RADIO AIDS TO NAVIGATION: NOTAM FILE ICT.
WICHITA (H) (H) VORTACW 113.8 ICT Chan 85 N37°44.72' W97°35.03' 112° 22.3 NM to fld. 1472/7E.
TACAN AZIMUTH unusable:
025°-035° blo 4,000'
040°-055° byd 20 NM
147°-159° blo 4,900'
VOR unusable:
025°-035° blo 4,000'
147°-159° blo 4,400'

RUSH CO (See LA CROSSE on page 109)