

LYNCHBURG**FALWELL** (W24) 3 SE UTC-5(-4DT) N37°22.68' W79°07.33'**CINCINNATI**

939 TPA—1739(800) NOTAM FILE DCA

L-261, 36G**RWY 10-28:** H2932X50 (ASPH) MIRL 4.7% up W**IAP****RWY 10:** Tree.**RWY 28:** TRCV(TRIL). Trees.**SERVICE:** S4 **FUEL** 100LL **LGT** ACTVT TRIL Rwy 28 CTAF.**AIRPORT REMARKS:** Attended 1200-2300Z†, Apr-Oct 1200-0000Z†. Deer on and in/ovf arpt. Land Rwy 28 (west) tkf Rwy 10 (east). Rwy 28 closed for take-off; Rwy 10 closed for landing.**AIRPORT MANAGER:** 434-845-8769**COMMUNICATIONS:** CTAF/UNICOM 123.0® **ROANOKE APP/DEP CON** 125.475 135.0**CLEARANCE DELIVERY PHONE:** For CD ctc Roanoke Apch at 540-563-1307.**RADIO AIDS TO NAVIGATION:** NOTAM FILE LYH.**LYNCHBURG (L) (L) VORW/DME** 109.2 LYH Chan 29 N37°15.27' W79°14.18' 041° 9.2 NM to fld. 871/5W.

VOR unusable:

020°-025°

200°-210°

301°-360°

COMM/NAV/WEATHER REMARKS: ROA twr svcs avbl at 540-563-1307.**LYNCHBURG RGNL/PRESTON GLENN FLD** (LYH)(KLYH) 5 SW UTC-5(-4DT) N37°19.52'**CINCINNATI**

W79°12.07'

H-10H, 12H, L-261, 36G

938 B ARFF Index—See Remarks NOTAM FILE LYH

IAP, AD**RWY 04-22:** H7100X150 (ASPH-GRVD) S-90, D-108, 2D-170 PCR 500 F/D/X/T HIRL

0.6% up NE

RWY 04: MALSR. PAPI(P4L)—GA 3.0° TCH 55'. RVR-T**RWY 22:** REIL. PAPI(P4L)—GA 3.0° TCH 45'. RVR-R**RWY 17-35:** H3386X75 (ASPH) S-25, D-35, 2D-55 MIRL No Part 121/Part 380 Ops**RWY 17:** REIL. PAPI(P2L)—GA 4.0° TCH 16'.**RWY 35:** REIL. PAPI(P2L)—GA 4.0° TCH 17'.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 04:** TORA-7100 TODA-7100 ASDA-6800 LDA-6800**RWY 17:** TORA-3386 TODA-3386 ASDA-3386 LDA-3386**RWY 22:** TORA-7100 TODA-7100 ASDA-7100 LDA-7100**RWY 35:** TORA-3386 TODA-3386 ASDA-3386 LDA-3386**SERVICE:** S4 **FUEL** 100LL, JET A **OX3** **LGT** When twr clsd ACTVT MALSR Rwy 04, HIRL Rwy 04-22 and twy lgts—CTAF.

REIL Rwy 17-35; PAPI Rwy 17-35; MIRL Rwy 17-35 unavbl when ATCT clsd. Rwy 04-22 PAPI lighted 24 hrs.

AIRPORT REMARKS: Attended 1000-0459Z†. Birds and other wildlife on and in/ovf arpt. All sfcs work in progress

mowing/maintenance. Extensive flight training on and in/ovf arpt. Class I, ARFF Index B. Twy G uncontrolled not visible from ATCT. Twy G clsd to air carrier and acft over 12,500 lbs. Rwy 17-35 PPR for acft over 12,500 lbs. Rwy 17-35 300 ft overrun each end.

AIRPORT MANAGER: 434-455-6090**WEATHER DATA SOURCES:** ASOS (434) 205-0756 LAWRS.**COMMUNICATIONS:** CTAF 127.65 ATIS 119.8 UNICOM 122.95® **ROANOKE APP/DEP CON** 125.475 135.0**TOWER** 127.65 (1130-0330Z†) **GND CON** 121.9**CLEARANCE DELIVERY PHONE:** For CD when ATCT clsd ctc Roanoke Apch at 540-563-1307.**AIRSPACE:** CLASS D svc 1130-0330Z†; other times CLASS E.**RADIO AIDS TO NAVIGATION:** NOTAM FILE LYH.**BOJAR NDB (MHW/LOM)** 385 LY N37°15.75' W79°14.59' 036° 4.3 NM to fld. 804/8W. NDB unmonitored when ATCT closed.**(L) (L) VORW/DME** 109.2 LYH Chan 29 N37°15.27' W79°14.18' 027° 4.6 NM to fld. 871/5W.

VOR unusable:

020°-025°

200°-210°

301°-360°

ILS 110.1 I-LYH Rwy 04. Class IE. LOM BOJAR NDB. ILS mon 24 hr at AOCC.