

PENDLETON**EASTERN OREGON RGNL AT PENDLETON** (PDT)(KPDPT) P (ARNG) 3 NW UTC-8(-7DT) N45°41.71'**SEATTLE**
H-1C, L-13A
IAP, AD

W118°50.60'

1494 B NOTAM FILE PDT

RWY 08-26: H6301X150 (ASPH-PFC) S-115, D-132, 2D-210

PCN 34 F/B/Y/U HIRL

RWY 08: ODALS. VASI(V4R)—GA 3.0° TCH 35'. RVR-R Ground.**RWY 26:** MALSR. PAPI(P4L)—GA 3.0° TCH 48'. RVR-T**RWY 11-29:** H4808X100 (ASPH-GRVD) S-70, D-120, 2S-152, 2D-122 PCN 18 F/B/Y/U MIRL**RWY 11:** REIL. PAPI(P4L)—GA 3.0° TCH 46'.**RWY 29:** REIL. PAPI(P4R)—GA 3.0° TCH 48'.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 08:** TORA-6301 TODA-6301 ASDA-6301 LDA-6301**RWY 11:** TORA-4808 TODA-4808 ASDA-4808 LDA-4808**RWY 26:** TORA-6301 TODA-6301 ASDA-6301 LDA-6301**RWY 29:** TORA-4808 TODA-4808 ASDA-4808 LDA-4808**SERVICE:** S4 **FUEL** 100LL, JET A1+, MOGAS **LGT** When ATCT clsd
ACTVT MALSR Rwy 26; ODALS Rwy 08; REIL Rwy 11 & 29; VASI
Rwy 08, PAPI Rwy 11; HIRL Rwy 08-26; MIRL Rwy 11-29—CTAF.
Rwy 11-29 PCL for hi instst 5 clicks only. PAPI Rwy 29 opr consly.
REIL Rwy 11 OTS. REIL Rwy 29 OTS. **MILITARY— FUEL** (NC-100LL,
A1+ - Self svc avbl H24.)**AIRPORT REMARKS:** Attended 1400-0400Z†. Svcs avbl from FBO btn 0400-1400Z† by phone call 541-276-3313 or 541-310-9542. Self fueling cardlocks avbl 24 hrs. Clsd to unscheduled air carrier ops with more than 30 pax seats exc PPR 4 hrs call 541-276-4411. Deer on and invof arpt Apr and Aug especially mornings and evenings. Thld Rwy 29 nstd marking, portion of rwy to function as twy. Twy B clsd south of Twy A. Int of ramp and Rwy 29 north end of terminal bldg, area obstructed from view of twr by terminal bldg. Rwy 08-26 surface condition unmonitored 1400-0400Z†. Rwy 11-29 surface condition unmonitored 1400-0400Z†. Fgt dly UAS actvty (lge and small) inside and invof the CDAS.**AIRPORT MANAGER:** 541-276-7754**WEATHER DATA SOURCES:** ASOS 118.325 (458) 212-2168.**COMMUNICATIONS:** CTAF 119.7 UNICOM 122.95Ⓡ **SPOKANE APP/DEP CON** 133.15 (1400-0600Z†) other times ctcⓇ **SEATTLE CENTER** 132.6**TOWER** 119.7 (1400-0400Z†) **GND CON** 121.9**CLEARANCE DELIVERY PHONE:** When Apch clsd, for CD ctc Seattle ARTCC at 253-351-3694**AIRSPACE:** CLASS D svc 1400-0400Z†; other times CLASS E.**RADIO AIDS TO NAVIGATION:** NOTAM FILE PDT.**PENDLETON (VH) (H) VORTACW** 114.7 PDT Chan 94 N45°41.91' W118°56.32' 079° 4.0 NM to fld. 1575/14E.

VOR unusable:

057°-066° byd 40 NM

067°-078° byd 40 NM blo 29,000'

096°-106° byd 40 NM blo 8,300'

096°-106° byd 48 NM blo 18,000'


107°-117° byd 40 NM

118°-128° byd 40 NM blo 12,000'

118°-128° byd 75 NM

129°-207° byd 40 NM

ILS 110.3 I-PDT Rwy 26. Class IE. LOC and glideslope unmonitored when twr clsd.

COMM/NAV/WEATHER REMARKS: Emerg freq 121.5 not avbl at twr.**PINEHURST STATE** (24S) 1 SW UTC-8(-7DT) N42°06.61' W122°22.99'**KLAMATH FALLS**

3643 NOTAM FILE MMV

RWY 04-22: H2800X30 (ASPH) 2.0% up SW**RWY 04:** Trees.**RWY 22:** Trees.**AIRPORT REMARKS:** Unattended. Surface conditions not reported. Irregular winter maintenance. Arpt may be clsd by snow. Strong winds from any direction will likely cause low-level turbulence. Rwy 04-22 12 ft trees wi 25 feet of cntrln full len. Rwy 22 slopes up to the SW, with abrupt 4% rise on SW half of rwy. Owner advises contact Oregon Dept. of Aviation 503-378-4880 prior to use.**AIRPORT MANAGER:** 503-378-4880**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.**PITTSBURG LANDING** (See IMNAHA on page 177)