

LAKELAND**LAKELAND LINDER INTL** (LAL)(KLAL) 4 SW UTC-5(-4DT) N27°59.26' W82°01.14'**MIAMI**

142 B ARFF Index—See Remarks NOTAM FILE LAL

H-8H, L-21D, 24F**RWY 10-28:** H8500X150 (ASPH-GRVD) S-50, D-250, 2D-550, 2D/2D2-1120 PCR 460 F/A/X/T**IAP, AD**

HIRL CL

RWY 10: ALSF2. TDZL. PAPI(P4R)—GA 3.0° TCH 71'. RVR-TMR**RWY 28:** PAPI(P4L)—GA 3.0° TCH 71'. RVR-TMR Trees.**RWY 05-23:** H5000X150 (ASPH-GRVD) S-94, D-150 PCR 320 F/A/X/T HIRL No Part 121/Part 380 Ops**RWY 05:** PAPI(P4L)—GA 3.0° TCH 59'.**RWY 23:** PAPI(P4L)—GA 3.0° TCH 46'. Trees.**RWY 08-26:** 2208X60 (TURF) No Part 121/Part 380 Ops**RWY 08:** Thld dsplcd 362'. Trees.**RWY 26:** Thld dsplcd 556'. Hangar.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 05:** TORA-5000 TODA-5000 ASDA-5000 LDA-5000**RWY 08:** TORA-1650 TODA-2010 ASDA-2205 LDA-1845**RWY 10:** TORA-8500 TODA-8500 ASDA-8500 LDA-8500**RWY 23:** TORA-5000 TODA-5000 ASDA-5000 LDA-5000**RWY 26:** TORA-1845 TODA-2205 ASDA-2205 LDA-1650**RWY 28:** TORA-8500 TODA-8500 ASDA-8500 LDA-8500**SERVICE:** S4 FUEL 100LL, JET A OX1, 2 LGT Twy D, D1, & E1 unlgtd. PAPI Rwy 05 and 23, 10 and 28 oper cont.**AIRPORT REMARKS:** Attended continuously. Bird act on and invof arpt. Rwy 08-26 mkd with pavers. Class I, ARFF Index B.

Index C avbl upon req. PJE within 5 NM 18,000 blw SR-SS. 24 hr PPR or imt reporting upon ldg for acft equipped with

weather modification or geoengineering eqpt ctc ops 863-834-4911. USCBP user fee arpt; svc Thur-Mon,

1530-2400Z±. Fee chrgd outside of svc hours. Fee payable on site. User fee arpt.

AIRPORT MANAGER: 863-834-3298**WEATHER DATA SOURCES:** AWOS-3PT (863) 834-2030 LAWRS.**COMMUNICATIONS:** UNICOM 122.95 ATIS 118.025**Ⓡ TAMPA APP/DEP CON** 120.65 119.9**TOWER** 124.5 **GND CON** 121.4**AIRSPACE:** CLASS D.**RADIO AIDS TO NAVIGATION:** NOTAM FILE LAL.**(VH) (H) VORTACW** 116.0 LAL Chan 107 N27°59.17' W82°00.83' at fld. 134/1E.

TACAN AZIMUTH unusable:

321°-339° blo 6,000'

VOR unusable:

020°-045° byd 40 NM

060°-073° byd 40 NM blo 2,500'

060°-073° byd 56 NM

070°-100° byd 35 NM blo 1,400'

074°-090° byd 40 NM blo 2,600'

074°-090° byd 51 NM

197°-207° byd 40 NM blo 2,000'

197°-207° byd 49 NM

317°-324° byd 40 NM

325°-335° byd 40 NM blo 2,000'

325°-335° byd 57 NM blo 3,000'

325°-335° byd 61 NM

ILS/DME 110.1 I-LAL Chan 38 Rwy 10. Class IIIE.**SOUTH LAKELAND** (X49) 1 S UTC-5(-4DT) N27°56.00' W82°02.64'**MIAMI**

110 NOTAM FILE PIE

RWY 14-32: 2412X100 (TURF)**RWY 14:** Tree. Rgt tfc.**RWY 32:** Tree.**SERVICE:** S2**AIRPORT REMARKS:** Unattended, on call. Call arpt mgr 786-873-8283 for attendance. Ultralight activity on and invof arpt.

Arpt is emerg evac site. Watch for emerg acft and vehicles on rwy and invof arpt. No skydiving, PPC, or gyro ops without written permission from arpt owner. Rwy 14-32 white pails outline landing strip. Rwy 14-32 w pails mark thlds. Arpt has no ngt time ops. Turf rwys may hold water after rain. Rwy 14-32 road 97 ft to 100 ft south of centerline at full length of rwy.

AIRPORT MANAGER: 863-417-2177**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Tampa Apch at 813-371-7810.