

**CONCORD****BUCHANAN FLD** (CCR)(KCCR) 1 W UTC-8(-7DT) N37°59.38' W122°03.41'**SAN FRANCISCO**

26 B ARFF Index—See Remarks NOTAM FILE CCR

H-3B, L-2F, 3A, A

**RWY 01L-19R:** H5001X150 (ASPH-CONC-GRVD) S-83, D-121, 2S-114, 2D-189 PCR 330 F/C/X/T

IAP, AD

HIRL

**RWY 01L:** REIL. PAPI(P4L)—GA 4.0° TCH 40'. Tree.**RWY 19R:** MALS. PAPI(P4L)—GA 3.0° TCH 22'. Thld dsplcd 601'. Pole. Rgt tfc.**RWY 14L-32R:** H4602X150 (ASPH-CONC-GRVD) S-83, D-189, 2S-114, 2D-120 PCR 330 F/C/X/T MIRL**RWY 14L:** Thld dsplcd 301'. Road.**RWY 32R:** REIL. PAPI(P4R)—GA 4.0° TCH 40'. Thld dsplcd 350'. Tree. Rgt tfc.**RWY 14R-32L:** H2798X75 (ASPH) S-12.5 PCN 14 F/B/W/T No Part 121/Part 380 Ops**RWY 14R:** Road. Rgt tfc.**RWY 01R-19L:** H2770X75 (ASPH) S-17 PCN 12 F/B/W/U No Part 121/Part 380 Ops**RWY 01R:** Tree. Rgt tfc.**RWY 19L:** Tree.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 01L:**TORA-4701 TODA-5001 ASDA-4401 LDA-4401**RWY 01R:**TORA-2770 TODA-2770 ASDA-2770 LDA-2770**RWY 14L:**TORA-4601 TODA-4601 ASDA-4001 LDA-3701**RWY 14R:**TORA-2799 TODA-2799 ASDA-2799 LDA-2799**RWY 19L:**TORA-2770 TODA-2770 ASDA-2770 LDA-2770**RWY 19R:**TORA-5001 TODA-5001 ASDA-5001 LDA-4401**RWY 32L:**TORA-2799 TODA-2799 ASDA-2799 LDA-2799**RWY 32R:**TORA-4601 TODA-5081 ASDA-4481 LDA-4131**SERVICE:** S4 **FUEL** 100LL, JET A1+ **OX** 1, 2 **LGT** ACTIVATE MALS **Rwy 19R** 0600-1400Z±; PAPI **Rwy 01L**, **Rwy 19R**, and **Rwy 32R**—119.7. **Rwy 01L** PAPI does not provide obstruction clearance byd 4.0 NM from thld. **Rwy 32R** PAPI does not provide obstruction clearance byd 4.0 NM from thld. **REIL** **Rwy 01L** off when tower clsd.**NOISE:** Noise sensitive area practice noise abatement (fly quiet) procedures. Arpt has noise abatement procedures ctc arpt manager prior to arrival 925-608-8000.**AIRPORT REMARKS:** Attended 1500-0100Z±. Birds on and invof arpt, heaviest concentration Nov-Mar and after rainstorms. Arpt sfc conditions not monitored 0600-1500Z±. When twr clsd **Rwy 14L-32R**, **Rwy 14R-32L** and **Rwy 01R-19L** CLOSED. **Rwy 19R** standard left tfc when twr closed. Class IV, ARFF Index A. CLOSED to ACR ops with more than 30 psgr seats exc PPR; call amgr 925-681-4200. ARFF svc avbl 24 hrs with prior apvl from arpt admin. +8' fence 110' byd **Rwy 01L** TODA distance of 5010' and +7' fence 210' byd **Rwy 14L** TODA distance of 4601' along the extended rwy centerline. **Rwy 01R-19L** pavement has high severity block cracking, longitudinal and transverse cracking, patching and weathering. No training ops Mon-Fri 0600-1500Z±, Sat, Sun and holidays 0600-1600Z±. Ldg fee for commercial ops and tie down fee for overnight parking. NOTE: See Special Notices—Arrival Alert.**AIRPORT MANAGER:** 925-608-8000**WEATHER DATA SOURCES:** ASOS (925) 689-2077 LAWRS.**COMMUNICATIONS:** CTAF 119.7 ATIS 124.7 925-685-4567 UNICOM 122.95

Ⓡ TRAVIS APP/DEP CON 119.9

**CONCORD TOWER** 119.7 123.9 (1500-0600Z±) **GND CON** 121.9 **CLNC DEL** 118.025**AIRSPACE:** CLASS D svc 1500-0600Z±; other times CLASS G.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CCR.**CONCORD (T) (T) VORW/DME** 117.0 CCR Chan 117 N38°02.70' W122°02.71' 173° 3.4 NM to fld. 5/17E.

VOR unusable:

090°-115° byd 10 NM blo 3,500'

DME unusable:

090°-115° byd 10 NM blo 3,500'

**LDA/DME** 108.5 I-CCR Chan 22 **Rwy 19R.** LDA unmonitored when ATCT clsd.**COMM/NAV/WEATHER REMARKS:** When twr clsd call Travis apch ctl (SUU) clnc del 707-424-5111.**CORNING MUNI** (Ø04) 1 NE UTC-8(-7DT) N39°56.77' W122°10.27'**SAN FRANCISCO**

295 B NOTAM FILE RIU

**RWY 17-35:** H2699X60 (ASPH) S-12 MIRL**RWY 17:** REIL.**RWY 35:** REIL. Rgt tfc.**SERVICE:** S4 **OX** 3, 4 **LGT** ACTVT MIRL **Rwy 17-35**—CTAF.**AIRPORT REMARKS:** Attended 1600-0100Z±. FBO on arpt phone 530-586-8566. Medical/firefighting/agricultural helicopters in vicinity of arpt. Ultralight activity on and in vicinity of arpt. Arpt rstd to acct less than 12,500 lbs maximum tkf weight or less.**AIRPORT MANAGER:** 530-824-7025**COMMUNICATIONS:** CTAF/UNICOM 123.0**CLEARANCE DELIVERY PHONE:** For CD ctc Oakland ARTCC at 510-745-3380.