

**MURRAY FLD** (EKA)(KEKA) 3 E UTC-8(-7DT) N40°48.20' W124°06.77'

**KLAMATH FALLS**  
L-2H  
IAP

11 B TPA-811(800) NOTAM FILE OAK

**RWY 12-30:** H3011X75 (ASPH) S-19 MIRL

**RWY 30:** VASI(V2L)—GA 4.0° TCH 26'. Rgt tfc.

**SERVICE:** S4 FUEL 100LL LGT ACTVT VASI Rwy 30; MIRL Rwy 12-30—CTAF. Rwy 30 VGS I unusbl byd 6.5 NM due to trrn.

**AIRPORT REMARKS:** Unatndd. Be alert for birds invof arpt. Deer in vcnty of rwy. Be aware, CTAF freq shared with nearby arpt. Flight Notification Service (ADCUS) avbl. Landing fee: ctc arpt website for dtls, exemptions.

**AIRPORT MANAGER:** (707) 839-5402

**COMMUNICATIONS:** CTAF/UNICOM 122.7

® **SEATTLE CENTER APP/DEP CON** 124.85 306.3

**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE FOT.

**FORTUNA (L) (L) VORTACW** 114.0 FOT Chan 87 N40°40.28' W124°14.07' 016° 9.7 NM to fld. 392/19E.

VOR unusable:

060°-070° byd 35 NM blo 9,500'

150°-165° byd 25 NM blo 6,500'

165°-200° byd 25 NM blo 8,000'

280°-330° byd 20 NM blo 3,000'

330°-336° byd 20 NM

336°-350° byd 20 NM blo 3,000'

TACAN AZIMUTH unusable:

060°-070° byd 35 NM blo 9,500'

150°-165° byd 25 NM blo 5,500'

165°-200° byd 25 NM blo 8,000'

315°-325° byd 15 NM blo 5,500'


DME unusable:

060°-070° byd 35 NM blo 9,500'

150°-165° byd 25 NM blo 5,500'

165°-200° byd 25 NM blo 8,000'

315°-325° byd 15 NM blo 5,500'



**SAMOA FLD** (033) 2 W UTC-8(-7DT) N40°46.85' W124°12.74'

**KLAMATH FALLS**

20 TPA-820(800) LRA NOTAM FILE OAK

**RWY 16-34:** H2700X60 (ASPH) S-10 0.4% up N

**RWY 16:** Rgt tfc.

**AIRPORT REMARKS:** Unattended. Day use only; CLOSED nghts. Ultralight activity on and invof arpt. Be aware, CTAF freq shared with nearby arpt.

**AIRPORT MANAGER:** 707-441-4374

**COMMUNICATIONS:** CTAF 122.7

**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.