

CHICAGO/AURORA**AURORA MUNI** (ARR)(KARR) 38 W UTC-6(-5DT) N41°46.32' W88°28.54'**CHICAGO**

H-5E, L-28H, A

IAP, AD

712 B NOTAM FILE ARR

RWY 09-27: H6501X100 (CONC-GRVD) S-30, D-130, 2S-165 HIRL**RWY 09:** MALSR. PAPI(P4L)—GA 3.0° TCH 45'.**RWY 27:** REIL. PAPI(P4L)—GA 3.0° TCH 45'.**RWY 15-33:** H5503X100 (CONC-GRVD) D-130, 2S-165 HIRL**RWY 15:** REIL. PAPI(P4L)—GA 3.0° TCH 34'.**RWY 33:** MALSR. PAPI(P4L)—GA 3.0° TCH 48'.**RWY 18-36:** H3198X75 (ASPH) S-30 MIRL**RWY 18:** REIL. PAPI(P4L)—GA 3.0° TCH 30'.**RWY 36:** REIL. VASI(V4L)—GA 3.0° TCH 34'.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 09:** ASDA-6972**RWY 27:** ASDA-6460 LDA-6460**SERVICE:** S4 FUEL 100, JET A1 OX 1, 2, 3, 4 LGT ACTIVATE MALSR

Rwy 09, Rwy 33, REIL Rwy 18, 36, 15 and Rwy 27; twy lgts—CTAF.

When twr clsd HIRL Rwy 15-33 and Rwy 09-27 and MIRL Rwy 18-36 preset low ints: to increase ints and ACTVT—CTAF.

AIRPORT REMARKS: Attended 1200-0600Z†. Rwy 18-36 sfc several large cracks and vegetative growth. Seasonal crops in Part 77 surfaces Rwy 09-27 and 15-33.**AIRPORT MANAGER:** (630) 256-3120**WEATHER DATA SOURCES:** ASOS (630) 466-5649 LAWRS.**COMMUNICATIONS:** CTAF 120.6 ATIS 125.85 UNICOM FBO svcs 122.95 123.5

® CHICAGO APP/DEP CON 133.5

TOWER 120.6 (1300-0300Z†) **GND CON 121.7** **CLNC DEL 121.7** (When twr clsd)**AIRSPACE:** CLASS D svc 1300-0300Z†; other times CLASS G.**RADIO AIDS TO NAVIGATION:** NOTAM FILE DPA.**DUPAGE (VL) (L) VORW/DME 114.55** DPA Chan 92(Y) N41°53.42' W88°21.01' 216° 9.1 NM to fld. 802/2E.

VOR unusable:

042°-047° byd 40 NM

JOLIET (VH) (H) VORW/DME 112.3 JOT Chan 70 N41°32.79' W88°19.10' 330° 15.3 NM to fld.

591/2E. NOTAM FILE JOT.

VOR unusable:

072°-090° byd 34 NM blo 3,000'

130°-175° byd 40 NM

185°-190° byd 40 NM

230°-240° byd 40 NM blo 18,000'

230°-240° byd 43 NM

345°-060° byd 40 NM

ILS 108.9 I-ARR Rwy 09.**LOC/DME 111.15** I-ROF Chan 48(Y) Rwy 33.**COMM/NAV/WEATHER REMARKS:** Emerg frequency 121.5 not avbl at twr.