

GARDEN CITY RGNL (GCK)(KGCK) 8 SE UTC-6(-5DT) N37°55.65' W100°43.47'

WICHITA

2891 B ARFF Index—See Remarks NOTAM FILE GCK

H-5B, L-106, 15C

RWY 17-35: H7299X100 (CONC-GRVD) S-76, D-91, 2S-114, 2D-125

IAP, AD

PCR 270 R/D/W/T HIRL

RWY 17: REIL. VASI(V4L)—GA 3.0° TCH 39'.

RWY 35: MALSR. VASI(V4L)—GA 3.0° TCH 41'.

RWY 12-30: H5700X100 (CONC) S-48, D-60 PCR 290 R/D/W/T MIRL

RWY 12: REIL. PAPI(P2L)—GA 3.0° TCH 47'.

RWY 30: REIL. PAPI(P2L)—GA 3.0° TCH 46'.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 12: TORA-5700 TODA-5700 ASDA-5700 LDA-5700

RWY 17: TORA-7299 TODA-7299 ASDA-7299 LDA-7299

RWY 30: TORA-5700 TODA-5700 ASDA-5700 LDA-5700

RWY 35: TORA-7299 TODA-7299 ASDA-7299 LDA-7299

SERVICE: S4 FUEL 100LL JET A QX2 LGT ACTIVATE MIRL Rwy

12-30, HIRL Rwy 17-35, REIL Rwy 17, Rwy 12, Rwy 30 and MALSR
Rwy 35—CTAF. PAPI Rwy 12 and 30 on 24 hrs**AIRPORT REMARKS:** Attended 1300-0300Z†. For svc after hrs call620-275-5055. Class I, ARFF Index A. CLOSED to unscheduled air
carrier ops with more than 30 passengers seats except PPR 48 hrs call
arpt manager 620-276-1190/ 620-290-3810. ARFF Index Bprovided. Air carrier ops are not authorized in excess of 15 mins before
or after scheduled arrival/departure times without prior coordination with arpt manager and confirmation that ARFF is avbl
prior to ldg or tlf. In the event of an air carrier diversion or other irregular ops events, aircraft opr should contact arpt
manager 620-290-3810. Facility constraints include: lack of intl passenger processing facilities, ltd number of parking
positions and ltd terminal space for passengers. Rwy 35 designated the calm wind rwy. Twr blind spot on the North Twy
A hold bay.**AIRPORT MANAGER:** 620-276-1190**WEATHER DATA SOURCES:** ASOS 121.325 (620) 275-0803. LAWRS 1300-0300Z†.**COMMUNICATIONS:** CTAF 118.15 UNICOM 122.95

RCO 122.2 (WICHITA RADIO)

® KANSAS CITY CENTER APP/DEP CON 125.2

TOWER 118.15 (1300-0300Z†) GND CON 119.0

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Kansas City ARTCC at 913-254-8508.**AIRSPACE:** CLASS D svc 1300-0300Z†; other times CLASS E.**RADIO AIDS TO NAVIGATION:** NOTAM FILE GCK.


(VH) (H) VORTACW 113.3 GCK Chan 80 N37°55.14' W100°43.50' at fld. 2878/11E.

TACAN AZIMUTH unusable:

280°-010° blo 4,000'

280°-010° byd 11 NM

ILS 109.9 I-GCK Rwy 35. Class IB.

COMM/NAV/WEATHER REMARKS: FSS communications unreliable below 4400' at 40 NM.**GARDNER MUNI** (K34) 1 W UTC-6(-5DT) N38°48.41' W94°57.40'

KANSAS CITY

1040 B NOTAM FILE COU

L-101, A

RWY 17-35: 3224X60 (TURF) LIRL 0.3% up S

RWY 17: Tree.

RWY 35: Trees.

RWY 08-26: H2399X36 (ASPH) S-6 PCN 3/F/C/Y/U LIRL(NSTD)

RWY 08: Fence.

RWY 03-21: 1871X60 (TURF)

RWY 03: Tree.

SERVICE: S4 FUEL 100LL LGT Rwy 08-26 NSTD LIRL: 35 ft outboard
of rwy 240 ft spacings. Rwy 08 end, one light each side of rwy, Rwy

26 end, three lights outboard each side. Rwy 17-35 rwy end lgts NA.

AIRPORT REMARKS: Attended Mon-Fri 1400-2200Z†. Fuel 24 hrs
self-serve. Glider and ultralight activity on and invof arpt. Aces Rwy 17
thr via Rwy 08 ovrn. Rwy end 17: mkd with orange barrels. Rwy end
35: mkd with orange barrels.**AIRPORT MANAGER:** 913-856-0914**COMMUNICATIONS:** CTAF/UNICOM 122.8**® KANSAS CITY APP/DEP CON 118.9****CLEARANCE DELIVERY PHONE:** For CD ctc Kansas City Apch at

816-329-2710.

RADIO AIDS TO NAVIGATION: NOTAM FILE TOP.

TOPEKA (VL) (L) VORTACW 117.8 TOP Chan 125 N39°08.22' W95°32.95' 120° 34.1 NM to fld. 1075/5E.

