

WARREN-SUGARBUSH (ØB7) 2 E UTC-5(-4DT) N44°07.04' W72°49.62'

MONTREAL

1470 NOTAM FILE BTV

RWY 04-22: H2575X30 (ASPH) S-8.5 0.5% up SW**RWY 04:** Trees. Rgt tfc.**RWY 22:** Trees.**SERVICE:** FUEL 100LL**AIRPORT REMARKS:** Attended May-Oct 1400-2300Z±. Arpt CLOSED Nov-Apr. 100LL fuel self svc only durg atnnd hrs.

Extensive glider activity on arpt sfc to 18000 ft dalgt hrs. No line of sight between rwy ends. TGLS NA. Grass areas not authorized for taxi, takeoffs and ldg without first checking UNICOM or management for field conds.

AIRPORT MANAGER: 802-496-2290**COMMUNICATIONS:** CTAF/UNICOM 123.0**CLEARANCE DELIVERY PHONE:** For CD ctc Burlington Apch at 802-657-4413, when Apch clsd ctc Boston ARTCC at 603-879-6859.**WEST DOVER****DEERFIELD VALLEY RGNL** (4V8) 1 SW UTC-5(-4DT) N42°55.63' W72°51.94'

NEW YORK

1953 NOTAM FILE BTV

RWY 01-19: H2650X75 (ASPH) MIRL**RWY 01:** Trees.**RWY 19:** Trees.**AIRPORT REMARKS:** Unattended. Rwy 01-19 debris on rwy, extsv cracking.

No ln of sight btw rwy ends. 60 ft drop off, 60 ft fm rwy end. Rwy 19:

-60 ft drop off, 60 ft fm rwy end. Ldg fee.

AIRPORT MANAGER: 281-788-8450**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓡ **BOSTON CENTER APP/DEP CON** 123.75**CLEARANCE DELIVERY PHONE:** For CD ctc Boston ARTCC at 603-879-6859.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BTV.**CAMBRIDGE (VL) (L) VORW/DME** 115.0 CAM Chan 97 N42°59.66'

W73°20.64' 115° 21.5 NM to fld. 1490/14W.

DME unusable:

040°-130° blo 9,000'

VOR unusable:

011°-021° byd 42 NM

022°-127° byd 40 NM

128°-144°


145°-160° byd 40 NM

161°-182°

183°-194° byd 40 NM

195°-205°

320°-010° byd 40 NM

**WILLIAM H MORSE STATE** (See BENNINGTON on page 323)