

HELENA RGNL (HLN)(KHLN) P (ARNG) 2 NE UTC-7(-6DT) N46°36.40' W111°59.00' **GREAT FALLS**
 3877 B LRA ARFF Index—See Remarks NOTAM FILE HLN MON Airport **H-1D, L-13C**
RWY 09-27: H9000X150 (ASPH-PFC) D-160, 2S-175, 2D-250, 2D/2D2-420 PCR 790 F/D/X/T HIRL **IAP, DIAP, AD**
RWY 09: REIL. PAPI(P4L)—GA 3.3° TCH 55'. Ground. 0.3% down.
RWY 27: MALSR. PAPI(P4L)—GA 3.0° TCH 55'. Rgt tfc.
RWY 05-23: H4644X75 (ASPH-PFC) S-21, D-30 PCR 300 F/D/X/T MIRL 1.2% up SW No Part 121/Part 380 Ops
RWY 05: PAPI(P2L)—GA 3.0° TCH 40'. Road.
RWY 23: PAPI(P2L)—GA 3.0° TCH 49'. Fence. Rgt tfc.
RWY 17-35: H2989X75 (ASPH-PFC) PCR 460 F/D/X/T MIRL 1.7% up SE No Part 121/Part 380 Ops
RWY 17: REIL.
RWY 35: REIL. Ground. Rgt tfc.
RWY 10-28: 1584X75 (TURF) 0.3% up W
RUNWAY DECLARED DISTANCE INFORMATION
RWY 05: TORA-4644 TODA-4644 ASDA-4644 LDA-4644
RWY 09: TORA-9000 TODA-9000 ASDA-9000 LDA-9000
RWY 17: TORA-2989 TODA-2989 ASDA-2989 LDA-2989
RWY 23: TORA-4644 TODA-4644 ASDA-4644 LDA-4644
RWY 27: TORA-9000 TODA-9000 ASDA-9000 LDA-9000
RWY 35: TORA-2989 TODA-2989 ASDA-2989 LDA-2989
SERVICE: S4 **FUEL** 100, 100LL, JET A **OX 1, 3** **LGT** When ATCT clsd ACTVT MALSR Rwy 27, REIL Rwy 09, 17 and 35;
 PAPI Rwy 09 and Rwy 27; HIRL Rwy 09-27; MIRL Rwy 05-23 and 17-35—CTAF. **MILITARY—FUEL**
 Svc—(406)442-2190
AIRPORT REMARKS: Attended 1200-0800Z†. Fuel svc-406-442-2190. Cold temperature airport. Altitude correction required
 at or below -16C. Twy A, B, and C btn Twy A and Rwy 35 not avbl to ACR grt than 30 pax seats. Class I, ARFF Index B.
 ARFF pvdd for sked Part 121 ACR; otrw prior apvl rqrd—amgr. Rwy 05-23 no Part 121/380 ops exc btn Twy F and Rwy
 09-27. Rwy 17-35 no Part 121/380 ops exc btn Twy F and Twy C. SAID in use. Operate transponders with altitude
 reporting mode and ADS-B (if equipped) enabled on all airport surfaces. Landing Rights Arpt (LRA):
 Cust—(406)-449-5506. Lndg fee grt than 10,000 lbs. Flight Notification Service (ADCUS) avbl.
MILITARY REMARKS: ARNG Ops 1400-0030Z† Mon-Fri, exc hol. Ctn durg tax; AASF ramp not stressed for large acft. Ramp
 advsy—126.2, D406-324-5775, C406-324-5775. Tsnt svc NA aft 2300Z† Mon-Fri, wkend and hol. Ft Harrison AAF
 wi Class D; PAJA—MT ARNG Ops C406-324-5775/76, D324-5775/76.
AIRPORT MANAGER: 406-442-2821
WEATHER DATA SOURCES: ASOS 120.4 (406) 290-3397.
COMMUNICATIONS: CTAF 118.3 ATIS 120.4 **UNICOM** 122.95
RCO 122.2 (GREAT FALLS RADIO)
 ® **APP/DEP CON** 119.5 229.4 (1300-0500Z†)
 ® **SALT LAKE CENTER APP/DEP CON** 133.4 285.4 (0500-1300Z†)
TOWER 118.3 257.8 (1300-0500Z†) **GND CON** 121.9
ARNG OPS 40.65 126.2 321.45
CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Salt Lake ARTCC at 801-320-2568.

CONTINUED ON NEXT PAGE

CONTINUED FROM PRECEDING PAGE

AIRSPACE: CLASS D svc 1300-0500Z†; other times CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE HLN.

(VH) (H) VORTACW 117.7 HLN Chan 124 N46°36.41' W111°57.21' 258° 1.2 NM to fld. 3826/12E.

VOR unusable:

039°-054° byd 35 NM blo 12,000'
 074°-084° byd 40 NM blo 28,000'
 086°-090° byd 40 NM
 091°-101° byd 40 NM blo 18,000'
 102°-108° byd 47 NM
 102°-108° byd 40 NM blo 10,800'
 109°-169° byd 25 NM blo 17,000'
 166°-258° byd 40 NM
 169°-189° byd 25 NM blo 13,500'
 189°-234° byd 25 NM blo 13,500'
 207°-217° byd 22 NM blo 13,000'
 234°-274° byd 25 NM blo 12,500'
 259°-263° byd 40 NM blo 13,000'
 259°-279° byd 60 NM blo 18,000'
 259°-279° byd 65 NM blo 28,000'
 280°-293° byd 40 NM
 294°-304° byd 87 NM
 298°-308° byd 40 NM blo 15,500'
 309°-334° byd 40 NM
 335°-345° byd 40 NM blo 9,500'
 335°-345° byd 56 NM

TACAN AZIMUTH unusable:

039°-074° byd 35 NM blo 13,000'
 109°-154° byd 15 NM
 154°-169° byd 15 NM blo 17,000'
 169°-189° byd 25 NM blo 13,500'
 189°-214° byd 15 NM
 204°-354° byd 25 NM blo 14,000'
 214°-254° byd 15 NM blo 17,500'
 324°-039° byd 25 NM blo 13,000'

DME unusable:

035°-070° byd 35 NM blo 13,000'
 105°-210° byd 25 NM
 109°-154° byd 25 NM
 109°-214° byd 15 NM blo 11,000'
 109°-214° byd 20 NM blo 12,000'
 154°-169° byd 25 NM blo 17,000'
 165°-185° byd 25 NM blo 13,500'
 189°-214° byd 25 NM
 207°-217° byd 22 NM blo 13,000'
 214°-254° byd 15 NM blo 12,000'
 214°-254° byd 25 NM blo 17,000'
 250°-300° byd 25 NM blo 14,000'
 320°-035° byd 25 NM blo 13,000'

VOR unusable:

360°-069° byd 40 NM
 342°-359° byd 40 NM

HAUSER NDB (MHW) 386 HAU N46°34.13' W111°45.48' 272° 9.6 NM to fld. 4026/12E. NDB unmonitored when HLN ATCT clsd.

ILS 110.1 I-HLN Rwy 27. Class IE. Unmonitored when ATCT closed. Localizer backcourse unusable byd 22° rgt of course, unusable within 2.7 DME.

HELLER FARM (See WINIFRED on page 150)
