

**CLE ELUM****CLE ELUM MUNI** (S93) 1 E UTC-8(-7DT) N47°11.65' W120°53.04'

SEATTLE

1945 B NOTAM FILE SEA

**RWY 07-25:** H2379X60 (ASPH) MIRL 0.3% up W**RWY 07:** REIL. PAPI(P2L)—GA 4.0° TCH 20'. Rgt tfc.**RWY 25:** REIL. PAPI(P2L)—GA 4.0° TCH 20'.**SERVICE:** LGT ACTVT REIL Rwy 07 and 25; MIRL Rwy 07-25—CTAF. PAPI Rwy 07 and 25 oper cons. ACTVT rotg bcn—CTAF.**AIRPORT REMARKS:** Unattended. Wildlife on and invof rwy. Ditch 75' ft fm cntrln runs len of northside of rwy. Rwy 07-25 markings are faded.**AIRPORT MANAGER:** 509-674-2262**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.**COMM/NAV/WEATHER REMARKS:** Gliders use CTAF freq 122.3.**DE VERE FLD** (2W1) 3 E UTC-8(-7DT) N47°10.65' W120°51.16'

SEATTLE

1800 NOTAM FILE SEA

**RWY 08-26:** H2055X30 (ASPH)**RWY 08:** Trees. Rgt tfc.**RWY 26:** Trees.**AIRPORT REMARKS:** Attended dalgt hrs. Fld occasionally CLOSED in winter. Wildlife on and invof rwy. Rwy 08-26 has 2 inch dropoff along entr rwy both sides. Rwy 08-26 svr unsealed cracks and joints. Rwy 08-26 NSTD mrkgs no nrs, small and square aiming points painted on rwy ends. All patterns to the south. Rwy 08-26 mrkgs faded.**AIRPORT MANAGER:** 509-962-2066**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.**COLFAX****LOWER GRANITE STATE** (ØØW) 12 S UTC-8(-7DT) N46°40.37' W117°26.50'

SEATTLE

719 NOTAM FILE SEA

**RWY 14-32:** 3400X50 (GRVL) 0.9% up SE**RWY 14:** Trees.**RWY 32:** Hill.**AIRPORT REMARKS:** Unattended. Vehicles; pedestrians, and animals on and invof rwy. No winter snow removal ops. Grvl portions of rwy sfc rough and soft. Steep drop off on both sides of runway.**AIRPORT MANAGER:** (360) 618-2477**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.**PORT OF WHITMAN BUSINESS AIR CENTER** (S94) 3 SW UTC-8(-7DT) N46°51.52' W117°24.84'

SEATTLE

2181 B TPA—3010(829) NOTAM FILE SEA

L-13B

**RWY 08-26:** H3209X60 (ASPH) S-17 MIRL 1.0% up E**RWY 08:** Thld dspcd 492'. Road.**RWY 26:** Thld dspcd 450'. Hill.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 08:** TORA-3209 TODA-3209 ASDA-3209 LDA-2718**RWY 26:** TORA-3209 TODA-3209 ASDA-3209 LDA-2890**SERVICE:** LGT ACTIVATE MIRL Rwy 08-26—CTAF.**AIRPORT REMARKS:** Attended Jan-Dec 1600-0000Z†. Deer invof rwy. Watch for birds invof creek south of arpt. Rwy 08-26 farm machinery may be opr in flds on both sides of rwy and off both rwy ends. 30' bldg 250' south AER 26. Dense agricultural ops Feb-Oct.**AIRPORT MANAGER:** 509-397-2061**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.**RADIO AIDS TO NAVIGATION:** NOTAM FILE PUW.**PULLMAN (VL) (L) VORW/DME** 117.15 PUW Chan 118(Y) N46°40.45' W117°13.41' 305° 13.6 NM to fld. 2772/20E. DME unmonitored.

DME unusable:

040°-045° byd 35 NM blo 8,000'

065°-070° byd 30 NM blo 7,000'

090°-095° byd 35 NM blo 7,000'

VOR unusable:

032°-100° byd 40 NM

155°-195° byd 40 NM