

DARRINGTON MUNI (1S2) 0 N UTC-8(-7DT) N48°15.52' W121°36.61'

SEATTLE

553 B NOTAM FILE SEA

RWY 10-28: H2491X40 (ASPH) MIRL**RWY 10:** Trees.**RWY 28:** Road.**SERVICE:** LGT ACTVT MIRL Rwy 10-28—CTAF. Arpt bcn OTS.**AIRPORT REMARKS:** Unattended. CLOSED when snow on rwy. Turbulence on hot days ldg west in trns east apch. Twys marked with blue reflectors. Twys rough pavement with swales and depressions.**AIRPORT MANAGER:** 360-631-1928**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.**DAVENPORT** (68S) 1 W UTC-8(-7DT) N47°39.12' W118°10.43'

SEATTLE

2424 B NOTAM FILE SEA

RWY 06-24: H3260X60 (ASPH) MIRL 0.3% up NE**RWY 06:** PAPI(P2L)—GA 4.0° TCH 22'.**RWY 24:** PAPI(P2L)—GA 4.0° TCH 21'. Rgt tfc.**SERVICE:** FUEL 100LL LGT MIRL Rwy 06-24 on SS-SR; PAPI Rwy 06 and Rwy 24 on consly.**AIRPORT REMARKS:** Attended on call. Mon-Fri 8:00 am to 5:00 pm, call office number, 509-725-4352. After hours call 509-721-0069. Fuel 24 hr credit card svc avbl. Pilots bring own ropes.**AIRPORT MANAGER:** 509-725-4352**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Spokane Apch at 509-742-2522**RADIO AIDS TO NAVIGATION:** NOTAM FILE GEG.**SPOKANE (VH) (H) VORTACW** 115.5 GEG Chan 102 N47°33.90' W117°37.61' 269° 22.8 NM to fld. 2756/14E.

VOR unusable:

007°-022° byd 26 NM blo 7,000'

029°-041° byd 40 NM

307°-337° byd 30 NM blo 9,000'

342°-007° byd 18 NM blo 7,000'

342°-007° byd 25 NM

DE VERE FLD (See CLE ELUM on page 227)**DEER PARK** (DEW)(KDEW) 3 NE UTC-8(-7DT) N47°58.02' W117°25.72'

SEATTLE

2211 B TPA—See Remarks NOTAM FILE DEW

H-1C, L-13B

RWY 16-34: H6101X75 (ASPH) S-30, D-50 MIRL 0.4% up NW

IAP

RWY 16: REIL. PAPI(P4L)—GA 3.5° TCH 38'. Trees.**RWY 34:** REIL. PAPI(P4L)—GA 3.0° TCH 40'.**RWY 05-23:** H3200X60 (ASPH) S-12.5 PCN 17 F/C/W/T**SERVICE:** S4 FUEL 100LL, JET A LGT ACTIVATE REIL Rwy 16 and Rwy 34; MIRL Rwy 16-34—CTAF. PAPI Rwy 16 and 34 opr continuously.**NOISE:** NS ABTMT procedures in effect ctc arpt mgr 509-276-3379.**AIRPORT REMARKS:** Attended Apr-Oct 1600-0100Z†, Nov-Mar 1800-0000Z†. 100LL and Jet A avbl 24 hrs credit card self svc facility. Call ahead for full svc, Jet A svc 509-276-3379. Rwy 05-23 heavy glider activity weekends. Model airplane activity on arpt. Farming opr active on land adjacent to rwys. Coyotes on and invof rwys. Rwy 16 and Rwy 34 rwy mrkgs faded. Monitor glider tfc on 123.3 abv 5000' MSL. Glider pattern TPA 3211(1000). 175' twr 2000' west of Rwy 16-34. Rwy 16 preferred calm wind rwy.**AIRPORT MANAGER:** 509-276-3379**WEATHER DATA SOURCES:** ASOS 135.175 (509) 276-2303.**COMMUNICATIONS:** CTAF/UNICOM 123.0

Ⓡ SPOKANE APP/DEP CON 123.75

CLEARANCE DELIVERY PHONE: For CD ctc Spokane Apch at 509-742-2522**AIRSPACE:** CLASS E.**RADIO AIDS TO NAVIGATION:** NOTAM FILE GEG.**SPOKANE (VH) (H) VORTACW** 115.5 GEG Chan 102 N47°33.90' W117°37.61' 004° 25.4 NM to fld. 2756/14E.

VOR unusable:

007°-022° byd 26 NM blo 7,000'

029°-041° byd 40 NM

307°-337° byd 30 NM blo 9,000'

342°-007° byd 18 NM blo 7,000'

342°-007° byd 25 NM

NDB (MHW) 365 DPY N47°58.06' W117°25.58' at fld. 2194/16E. NOTAM FILE DEW. NDB unmonitored.