



**WARDEN** (2S4) 1 W UTC-8(-7DT) N46°57.95' W119°03.98'  
 1276 B NOTAM FILE SEA  
**RWY 17-35:** H2811X60 (ASPH) MIRL  
**RWY 17:** SAVASI(S2R). Thld dspclcd 560'.  
**SERVICE:** LGT SS-SR.  
**AIRPORT REMARKS:** Unattended. CAUTION: Structures and irrigation material in pri apch sfc. Roads parll both sides of rwy. Rwy 17-35 320' grvl ovrn south end. Rwy 17-35 centerline paint chipping. No rwy numbers. Grvl apron cond good. Pilots bring own ropes.  
**AIRPORT MANAGER:** 509-750-4634  
**COMMUNICATIONS:** CTAF 122.9  
**CLEARANCE DELIVERY PHONE:** For CD ctc Grant County Apch at 509-762-2842, when Apch clsd ctc Seattle ARTCC at 253-351-3694.

SEATTLE



**WATERVILLE** (2S5) 1 NE UTC-8(-7DT) N47°39.36' W120°03.39'  
 2645 B NOTAM FILE SEA  
**RWY 07-25:** H2978X50 (ASPH) S-5 LIRL  
**RWY 07:** Thld dspclcd 270'. Road.  
**RUNWAY DECLARED DISTANCE INFORMATION**  
**RWY 07:** TORA-2800 TODA-2800 LDA-2500  
**RWY 25:** TORA-2500 TODA-2500 LDA-2500  
**AIRPORT REMARKS:** Unattended. Hill on S side of rwy in tran sfc. Rwy shoulders soft in wet weather.  
**AIRPORT MANAGER:** 509-884-4700  
**COMMUNICATIONS:** CTAF 122.9  
**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.

SEATTLE



**WATON** N48°04.57' W122°09.23' NOTAM FILE AWO.  
**NDB (LOMW)** 382 AW 341° 5.1 NM to Arlington Muni. 65/17E.

SEATTLE