

BILLINGS LOGAN INTL (BIL)(KBIL) 2 NW UTC-7(-6DT) N45°48.47' W108°32.61'**BILLINGS**

3662 B TPA—See Remarks ARFF Index—See Remarks NOTAM FILE BIL

H-1E, L-13D**RWY 10L-28R:** H10518X150 (ASPH-GRVD) S-120, D-214, 2S-175, 2D-365 PCR 745 F/B/X/T HIRL**IAP, AD****RWY 10L:** MALSR. PAPI(P4L)—GA 3.0° TCH 51'. RVR-T 0.8% down.**RWY 28R:** REIL. PAPI(P4R)—GA 3.0° TCH 56'. RVR-R Ground. 1.0% up.**RWY 07-25:** H5501X75 (ASPH-GRVD) S-12.5 PCR 303 F/B/X/T MIRL 1.9% up SW**RWY 07:** PAPI(P4L)—GA 3.0° TCH 31'. Ground.**RWY 25:** REIL. PAPI(P4R)—GA 3.0° TCH 36'.**RWY 10R-28L:** H3800X75 (ASPH) S-12.5 PCR 107 F/B/X/T MIRL 1.3% up NW**RWY 10R:** Ground.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 07:** TORA-5501 TODA-5501 ASDA-5501 LDA-5501**RWY 10L:** TORA-10518 TODA-10518 ASDA-10518 LDA-10518**RWY 10R:** TORA-3801 TODA-3801 ASDA-3801 LDA-3801**RWY 25:** TORA-5501 TODA-5501 ASDA-5501 LDA-5501**RWY 28L:** TORA-3801 TODA-3801 ASDA-3801 LDA-3801**RWY 28R:** TORA-10518 TODA-10518 ASDA-10518 LDA-10518**SERVICE:** S4 **FUEL** 100LL, **JET A** **OX** 1, 2, 3, 4 **LGT** For MIRL Rwy 10R-28L and Rwy 07-25, HIRL Rwy 10L-28R, MALSR Rwy 10L and REIL Rwy 25 and Rwy 28R ctc twr.**AIRPORT REMARKS:** Attended continuously. Migratory waterfowl invof arpt. Pilots conducting EFVS ops; be aware LED ALS in use Rwy 10L. SAID in use. Operate transponders with altitude reporting mode and ADS-B (if equipped) enabled on all airport surfaces. Rwy 07-25 and Rwy 10R-28L clsd to acft over 12,500 lbs. No cstrms, remote acft parking, ltd gnd handling svc. Twy D 35' wide clsd to acft over 12,500 lbs. Class I, ARFF Index C. PPR unscheduled air carrier ops with more than 30 pax seats ctc arpt ops 406-657-8496. ARFF Index B from 0900-1200Z±. 180° turns prohibited on all sfcs. TPA—Single engine acft 4500 (838), multi engine/turbojet acft 5000 (1338).**AIRPORT MANAGER:** (406) 657-8484**WEATHER DATA SOURCES:** ASOS 126.3 (406) 503-0719. LLWAS.**COMMUNICATIONS:** ATIS 126.3 **UNICOM** 122.95**(R) APP/DEP CON** 119.2 EAST 120.5 WEST**TOWER** 127.2 **GND CON** 121.9**PRE TAXI CLNC** 121.9**AIRSPACE:** CLASS C svc ctc **APP CON**.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BIL.**(VH) (H) VORTACW** 114.5 BIL Chan 92 N45°48.51' W108°37.48' 077° 3.4 NM to fld. 3811/14E.

VOR unusable:

146°-154° byd 40 NM

155°-165° byd 40 NM blo 11,000'

155°-165° byd 49 NM blo 18,000'

166°-173° byd 40 NM

ILS/DME 111.5 I-BIL Chan 52 Rwy 10L. Class IT.**ILS/DME** 111.5 I-BMO Chan 52 Rwy 28R. Class IA. Localizer unusable beyond 20 degrees left and right of course.**BLACK BUTTE NORTH** (See WINIFRED on page 149)**BOULDER** (3U9) 2 S UTC-7(-6DT) N46°12.70' W112°06.46'**GREAT FALLS**

4968 NOTAM FILE GTF

RWY 11-29: 3675X72 (TURF) 1.6% up W**AIRPORT REMARKS:** Unattended. No snow removal. Rwy 11-29 NSTD markings, thlds and edges marked with white cones.

-2' drainage ditch +1' berm west side of rwy full length, 43' from Rwy 11-29 cntrln.

AIRPORT MANAGER: (406) 431-7519**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Helena Apch at 406-449-5756/5761, when Apch clsd ctc Salt Lake ARTCC at 801-320-2568.**BOWMAN FLD** (See ANACONDA on page 90)