

## SAIPAN ISLAND

COMMONWEALTH HEALTH CENTER HELIPORT (C21) 1 E UTC+10

HAWAIIAN—MARIANA

N15°12.59' E145°43.47'

16 NOTAM FILE HNL Not insp.

HELIPAD H1: H45X45 (CONC)

HELIPORT REMARKS: Attended continuously. Rwy H1 110' hotel bldgs west and 85' water tank east of helipad.

AIRPORT MANAGER: (670) 234-8950

COMMUNICATIONS: CTAF 125.7

FRANCISCO C ADA/SAIPAN INTL (GSN)(PGSN) 4 SW UTC+10 N15°07.21' E145°43.80'

HAWAIIAN—MARIANA

214 B TPA—See Remarks LRA Class I, ARFF Index D

P-1A

NOTAM FILE GSN

IAP

RWY 07-25: H8699X200 (ASPH-GRVD) S-87, D-175, 2D-350, 2D/2D2-690 PCR 715 F/A/X/T HIRL

RWY 07: MALSR. REIL. Rgt tfc.

RWY 25: REIL. PAPI(P4L)—GA 3.0° TCH 75'

RWY 06-24: H7001X100 (ASPH) PCN 67 R/A/X/T MIRL

RWY 06: Thld dsplcd 396'.

## RUNWAY DECLARED DISTANCE INFORMATION

RWY 06: TORA-7001 TODA-6800 ASDA-6645 LDA-6600

RWY 07: TORA-8699 TODA-8669 ASDA-8664 LDA-8010

RWY 24: TORA-6400 TODA-7001 ASDA-6302 LDA-7000

RWY 25: TORA-8699 TODA-8699 ASDA-8045 LDA-8010

SERVICE: FUEL 100, 100LL, JET A1+ LGT SS-SR. Rwy 07 VASI and glidepath not coincident.

AIRPORT REMARKS: Attended continuously. PPR from Executive Director Commonwealth Ports Authority Saipan call (670) 237-6500 Mon-Fri 2200-0700Z other times call 670-237-6535. For Apt Security call (670) 237-6529.

Immigration and Customs available during scheduled operations. Other times prior arrangements must be made with CBP port director call (670) 288-0025/26. Rwy 06-24 open for taxiing only (not avbl for lng and tkof). Open for ldg and tkof when Rwy 07-25 clsd. Class I, ARFF Index D. Clsd to unsked ACR opns with more than 30 psgr seats exc PPR call or write amgr 670-237-6500, P.O. Box 501055 Saipan MP 96950. TPA—Traffic pattern altitude for large and turbine powered acft 1699(1485), small aircraft 1199(985).

AIRPORT MANAGER: (670) 237-6500

WEATHER DATA SOURCES: ASOS (670) 288-5017. SAWRS.

COMMUNICATIONS: ATIS 127.2

Ⓡ GUAM CERAP APP/DEP CON 118.4

TOWER 125.7 GND CON 121.8

AIRSPACE: CLASS D svc

RADIO AIDS TO NAVIGATION:

SAIPAN NDB (HW) 312 SN N15°06.68' E145°42.62' 066° 1.2 NM to fld. 83/2E.

ILS/DME 109.9 I-GSN Chan 36 Rwy 07. Glideslope unusable byd 9 NM.

SAIPAN N15°06.68' E145°42.62' NOTAM FILE GSN

HAWAIIAN—MARIANA

NDB (HW) 312 SN 066° 1.2 NM to Francisco C Ada/Saipan Intl. 83/2E.

P-1A