

DIMMITT MUNI (T55) 2 N UTC-6(-5DT) N34°34.00' W102°19.36'

ALBUQUERQUE

3883 B NOTAM FILE FTW

H-6G, L-6H

RWY 01-19: H5500X60 (ASPH) S-15 MIRL

RWY 01: Tree.

RWY 19: Road. Rgt tfc.

SERVICE: FUEL 100LL LGT ACTVT MIRL Rwy 01-19-CTAF.

AIRPORT REMARKS: Unattended. For fuel call 806-647-2550 during business hrs. Rwy 01-19 Pavement spalling, cracks with vegetation growing through, loose stones and paint on sfc. Rwy 01 and 19 Markings peeling off pavement.

AIRPORT MANAGER: 806-647-2155

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Albuquerque ARTCC at 505-856-4861.

RADIO AIDS TO NAVIGATION: NOTAM FILE FTW.

TEXICO (VH) (H) VORTACW 112.2 TXO Chan 59 N34°29.71' W102°50.38' 069° 26.0 NM to fld. 4060/11E.

VOR unusable:

095°-100° byd 40 NM

120°-130° byd 40 NM

210°-272° byd 60 NM blo 10,000'

273°-283° byd 40 NM blo 6,000'

273°-283° byd 46 NM blo 7,000'


273°-283° byd 59 NM

284°-319° byd 40 NM

320°-035° byd 40 NM

TACAN AZIMUTH unusable:

222°-232°



DORCHESTER

TXAEROSPORT AERODROME (X65) 1 NE UTC-6(-5DT) N33°32.18' W96°40.83'

DALLAS-FT WORTH

855 NOTAM FILE FTW

RWY 17-35: 3200X100 (TURF)

RWY 17: Trees.

RWY 35: Road.

SERVICE: S4

AIRPORT REMARKS: Attended Mon-Fri 1300-2200Z±. Wildlife on and invof arpt. Rwy 17-35 mkd with orange tfc cones set at 70' wide.

AIRPORT MANAGER: 469-759-9976

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584.

DRAUGHON-MILLER CENTRAL TEXAS RGNL (See TEMPLE on page 448)