
GROVETON/TRINITY CO (33R) 3 NW UTC-6(-5DT) N31°05.06' W95°09.85' HOUSTON
 340 B NOTAM FILE CXO L-19E, 21A
RWY 16-34: H3500X60 (ASPH) S-8 LIRL
RWY 16: Trees.
RWY 34: Trees.
SERVICE: LGT ACTIVATE LIRL Rwy 16-34—CTAF.
AIRPORT REMARKS: Unattended. Deer and feral hogs on and invof arpt.
AIRPORT MANAGER: 936-642-1746
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Houston ARTCC at 281-230-5622.
RADIO AIDS TO NAVIGATION: NOTAM FILE LFK.
LUFKIN (VH) (H) VORTAC 112.1 LFK Chan 58 N31°09.75' W94°43.01' 254° 23.5 NM to fld. 207/5E.
 TACAN AZIMUTH unusable:
 260°-275° byd 30 NM
 275°-260° byd 30 NM blo 2,500'
 DME unusable:
 260°-275° byd 30 NM
 275°-260° byd 30 NM blo 2,500'
 VOR unusable:
 305°-312° byd 40 NM
 313°-323° byd 40 NM blo 2,300'
 313°-323° byd 66 NM
 324°-330° byd 40 NM

GRUVER MUNI (E19) 2 SW UTC-6(-5DT) N36°14.02' W101°25.93' WICHITA
 3205 B NOTAM FILE FTW L-15B
RWY 02-20: H4698X60 (ASPH) S-12.5 MIRL 0.4% up SW IAP
RWY 02: Fence.
SERVICE: LGT ACTVT MIRL Rwy 02-20—CTAF.
AIRPORT REMARKS: Unattended. Extsv pavement cracking, potholes at Rwy 20 thr. Rwy 02 and Rwy 29 mkgs faded.
AIRPORT MANAGER: 806-733-2424
COMMUNICATIONS: CTAF 122.9
 ® **ALBUQUERQUE CENTER APP/DEP CON** 127.85
CLEARANCE DELIVERY PHONE: For CD ctc Albuquerque ARTCC at 505-856-4861.
RADIO AIDS TO NAVIGATION: NOTAM FILE BGD.
BORGER (L) TACAN Chan 23 BGD (108.6) N35°48.42' W101°22.93' 344° 25.7 NM to fld. 3130/11E.
 TACAN AZIMUTH unusable:
 220°-320° byd 10 NM blo 12,000'

GUADALUPE PASS N31°49.97' W104°48.55' EL PASO
 RCO 122.5 (ALBUQUERQUE RADIO) L-6G

GUTHRIE VUF N33°38.23' W100°20.86'/1787 DALLAS-FT WORTH
 AWOS-3PT 120.20 (806) 596-4616 VUF AWOS-3PT is associated with 6666 Ranch airport 6TE6. L-17B

GUTHRIE N33°46.70' W100°20.17' NOTAM FILE FTW. DALLAS-FT. WORTH
 (L) DME 114.5 GTH Chan 92 010° 15.2 NM to Dan E Richards Muni. 1941. H-6G, L-17B

H H COFFIELD RGNL (See ROCKDALE on page 423)

HALE CO (See PLAINVIEW on page 413)

HALL-MILLER MUNI (See ATLANTA on page 266)
