

MIAMI—OPA LOCKA EXEC (OPF)(KOPF) P (CG) 10 N UTC-5(-4DT) N25°54.45' W80°16.69' **MIAMI**
 8 B LRA NOTAM FILE OPF **H-81, L-23C, A**
RWY 09L-27R: H8002X150 (ASPH-GRVD) S-120, D-249, 2S-175, 2D-484, 2D/2D2-1000 **IAP, AD**
 PCN 61 F/A/W/T HIRL
RWY 09L: MALSR. PAPI(P4L)—GA 3.0° TCH 55'. Trees.
RWY 27R: MALS. PAPI(P4L)—GA 3.0° TCH 58'. Trees. Rgt tfc.
RWY 12-30: H6800X150 (ASPH-GRVD) S-120, D-249, 2D-484, 2D/2D2-1000 PCN 61 F/A/X/T HIRL
RWY 12: MALSR. PAPI(P4L)—GA 3.0° TCH 53'. Thld dsplcd 800'. Trees.
RWY 30: PAPI(P4L)—GA 3.0° TCH 52'. Tree.
RWY 09R-27L: H4309X100 (ASPH-GRVD) S-96, D-154 PCN 36 F/A/Y/T MIRL
RWY 09R: VASI(V4L)—GA 3.0° TCH 26'. Pole. Rgt tfc.
RWY 27L: PAPI(P4L)—GA 3.5° TCH 52'. Trees.

RUNWAY DECLARED DISTANCE INFORMATION
RWY 09L: TORA-8002 TODA-8202 ASDA-8202 LDA-8002
RWY 09R: TORA-4306 TODA-4306 ASDA-4306 LDA-4306
RWY 12: TORA-6800 TODA-7800 ASDA-7000 LDA-6000
RWY 27L: TORA-4306 TODA-4306 ASDA-4306 LDA-4306
RWY 27R: TORA-8002 TODA-8202 ASDA-8202 LDA-8002
RWY 30: TORA-6800 TODA-7000 ASDA-7000 LDA-6800

SERVICE: S4 **FUEL** 100LL, JET A **OX** 1, 2, 3, 4 **LGT** When ATCT clsd ACTVT MALSR Rwy 12; PAPI Rwy 12 and 30; HIRL Rwy 12-30—CTAF. 30 min PPR to req actv'n of MALSR Rwy 09L; MALS Rwy 27R; PAPI Rwy 09L and 27R; HIRL Rwy 09L-27R—305-869-1660 and CTAF. Rwy 09L: PAPI unusbl byd 7 degs R of cntrl'n. **MILITARY—FUEL** J5 (PPR CG) A+ (C305-687-8410.) (NC-100LL, A) Contract fuel—305-685-4646. **FLUID** LHGX

NOISE: Noise sensitive arpt. Flt T is ltd to acft 40,000 lbs max gross tkof wt and blw & only btn 1200-0400Z†. Specific tfc pats are published for hel and fixed wing tfc; compliance is mandatory. Obtain info fm ATCT or FBO or amgr; or req specific tfc pat instructions on initial ctc. Rwy 09R-27L clsd dly 0400-1200Z† for acft noise abatement to srndg arpt community.

AIRPORT REMARKS: Attended continuously. Birds invof arpt. Dual tfc pats for hels and fixed wing acft in use Rwy 09R-27L. Acft with wingspans grtr than 117' are prohibited fm txig on Twy P btn Twy H and Twy N8. Hel arr and dep avoid flying over parked or by acft. All acft and vehicles should rpt psns to ATC by using the sfc painted spot nrs on all exits to the ramp and non-movement areas. Vehicle lane xing Twy E to the fire stn is non-movement. Twy C and B south of Twy P are non-movement areas. Twy T btn Twy E and Twy T8 rdcd spd rqrd for acft wingspan more than 117'. Twy R btn Twy F and G rstrd to acft with wingspan less than 94'. 24 hr PPR for acft equipped with weather modification or geoeengineering eqpt 305-869-1660. Flt Notification Svc (ADCUS) avbl 1300-0400Z†. NOTE: See Special Notices—Arrival Alert.

AIRPORT MANAGER: 305-869-1662
WEATHER DATA SOURCES: ASOS 125.9 (305) 681-4063. LAWRS.
COMMUNICATIONS: CTAF 134.675 **ATIS** 125.9

® **APP/DEP CON** 128.6
TOWER 134.675 (1200-0400Z†) **GND CON** 120.025 **CLNC DEL** 119.2
GCO (119.45)

CLEARANCE DELIVERY PHONE: For CD, if una via GCO, ctc Miami Apch at 305-869-5432.
AIRSPACE: CLASS D svc 1200-0400Z†; other times CLASS G.

RADIO AIDS TO NAVIGATION: NOTAM FILE MIA.

DOLPHIN (VH) (H) VORTAC 113.9 DHP Chan 86 N25°48.00' W80°20.94' 035° 7.5 NM to fld. 6/4W.
 TACAN AZIMUTH unusable:
 055°-065° byd 35 NM blo 3,000'
 185°-195° byd 23 NM
 226°-236° byd 35 NM
 DME unusable:
 055°-065° byd 35 NM blo 3,000'
 VOR unusable:
 034°-037° byd 40 NM
 090°-101° byd 40 NM blo 5,500'
 090°-101° byd 54 NM
 102°-111° byd 40 NM
ILS 110.5 I-OPF Rwy 09L. Class IB. LOC unmonitored when ATCT clsd. LOC unusable wi 0.2 NM. Autopilot cpd apch NA blw 770' MSL.
ILS/DME 111.55 I-OLX Chan 52(Y) Rwy 12. Autopilot cpd apch NA blw 500' MSL.
ILS/DME 111.35 I-PLJ Chan 50(Y) Rwy 27R. Class IA. Autopilot cpd apch NA blw 700' MSL. LOC unusable 0.3 NM inbnd.

MIAMI HOMESTEAD GENERAL AVIATION (See HOMESTEAD on page 117)

MIID—FLORIDA (See EUSTIS on page 106)